



FOR IMMEDIATE RELEASE
CONTACT: Michael Young, PIO, 623-238-0179

ELECTRONIC CIGARETTE CHARGER RESPONSIBLE FOR GLENDALE CAR FIRE

Glendale, Ariz. — Glendale Fire Investigators say a vehicle fire at 19000 North 67 Avenue on the afternoon of April 23 was caused when an electronic cigarette charger was left unattended in the vehicle's front charger. The electronic cigarette has a lithium battery which appeared to have exploded. The hot fragments were projected out between the two front seats, landing in the rear seat causing the interior to catch fire.

The Glendale Fire Department reminds residents to never leave any electronic device unattended while charging.



###