



March 28, 2008

Dear Pool Builders or Pool Owner:

The recent adoption of the 2005 National Electrical Code requires that we add an additional inspection for swimming pools to our current list of inspections.

Section 680.26 (C), regarding the Equipotential Bonding Grid, now requires that a #8 bond wire circle the entire pool within three feet of the waters edge and bond back to the pool grid. This bond wire is required to be 4 to 6 inches below the surface slab, or the cool decking. In order for the inspection department to verify that this wire is in place and correctly installed, we will be adding inspection number **674** for you to call, prior to placing the surfacing material in this area. You will call for this inspection, as you do all others through the IVR system, using number **674** as the number. All pools permitted on March 31, 2008 or later will be subject to this new inspection.

If you have any questions regarding this additional inspection, you may contact a Sr. Building Inspector at 623-930-2800.

Sincerely,

Pam Wertz
Assistant Building Safety Director
City of Glendale